## SHUTTLE CRITICAL FIEMS LIST - MSBLS GROUND STATION

SUBSYSTEM: GROUND STATION - MSRLS FMEA NO.: 05-2MO-00002 REV: 7 Sept 89 ASSEMBLY : Shelter ABORT: CRIT. FUNC: 1 P/N : 517070 CRIT. HDW: 1 VEHICLE 102 103 104 105 QUANTITY: 1 EFFECTIVITY: X Х Х Х PHASE(S) PL  $\mathbf{r}$ DO X LS  $\infty$ 

PREPARED BY:

DES: Menue Dulmorts

DES: Krue Dulmorts

REL: White Properties Rel: Government Properties

OE: Columbia Des: Colum

REDUNDANCY SCREEN: A-

B-

C-

ITEM: Shelter

FUNCTION: Provides Elevation guidance RF beam to Orbiter.

FAILURE MODE: Erroneous EL guidance RF is radiated to Orbiter from Shelter.

CAUSE(S): A Shelter IRU (EL subsystem) fails due to piece part electrical failure. The IRU's which can cause this failure mode (05-2MD-00002) are listed below, with IRU Designator No., IRU P/N, and IRU Name:

LRU P/N:	LRU Name:
513480	Digital Unit, Elevation
501808	Transmitter, Azimuth/DME
502333	Field Monitor Circuits, Elevation
501825	Power Supply
501772	Scanner, Elevation
395257	Antenna, Elevation
516994	Assy, Waveguide (Elevation)
513887	Radome, Elevation
517076	Panel, Entrance, Signal
517079	Cables, Interconn, Interior (inside Shltr)
517081	Harness, Rack
517082	Control Monitor
517080	Cables, Interconn, External (to/from Shltr)
513455	Panel, Entrance, Power
513456	Assy, Filter Box
518007	Assy, RF (Switching)
	513480 501808 501808 502333 501825 501772 395257 516994 513887 517076 517079 517081 517082 517080 513455 513456

EFFECT(S): (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE

(A/B) All RF output from the Shelter ceases, due to MSBIS shutdown.

- (C) No effect.
- (D) Possible loss of Crew/Vehicle due to degradation of the terminal area approach and landing functions.

#### SHITTLE CRITICAL FIEMS LIST - MSBLS GROUND STATION

SURSYSTEM: GROUND STATION - MSBLS FMEA NO.: 05-2MO-00002 REV: 7 Sept 89

#### DISPOSTION AND RATIONALE:

(A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE

# (A) - DESIGN

The MSBIS design was structured from existing/proven ground-based landing systems and upgraded to meet MIL-E-4158, MIL-STD-454 and all subsidiary specifications in effect at the time of manufacture. Military and standard NASA approved parts, materials and processes were used.

The design evolved from a timely and in-depth internal design review process culminating in an optimum reliability/maintainability/performance end-item product. The design review process included studies such as FMFA, electrical and thermal analysis, sneak circuit analysis, worst case studies, tolerance analysis, etc. which resulted in direct impact of the design.

The design was approved via the formal NASA-Eaton PDR, CDR, PCA, FCA and certification process.

#### (B) - TEST

The MSHIS program consists of an equipment confidence build-up approach starting from 100% screening of components (burn-in and environmental test). Environmental testing of SRU's and 100% temperature/vibration tests at the IRU and equipment rack-level.

In plant ATP for functional performance verification and workmanship will be performed and witnessed by Faton, NASA and AFPRO on all IRUs and again at system level.

Site testing and certification will be performed on each system after installation. Annual flight tests are conducted to demonstrate continued system compatibility.

Ground Turnaround Test - Verify operation of the MSBIS Ground Station prior to each Orbiter landing.

#### SHUTTLE CRITICAL ITEMS LIST - MSBLS GROUND STATION

SUBSYSTEM: GROUND STATION - MSHLS FMEA NO.: 05-2MO-00002 REV: 7 Sept 89

#### (C) - INSPECTION

## Receiving Inspection

Receiving inspection verifies all incoming parts and materials, including the performance of visual and dimensional examinations. All electrical, mechanical and raw material records that certify materials and physical properties per drawing/specification requirements are retained by receiving inspection as required by contract.

#### Assembly/Installation

All detailed inspections are planned out by the methodization department for all new builds, spares and repairs for the MSBIS Programs. Inspection points are designated to permit inspection before the applicable portions of the assembly become inaccessible and prior to the next assembly operation.

#### Critical Processes

All processes and certifications are monitored and verified by inspection. The critical processes are soldering, conformal coating, torquing and boresiting, application of adhesives/sealants and application of chemical film.

#### Testing

All parts of the ATP are observed and verified by QA.

## Handling/Packaging

All parts and assemblies are protected from damage or contamination from the point of receiving inspection to final shipment, through methods detailed in a documented procedure. This handling procedure is in effect for all newly built hardware as well as for repair units. QA audits conformance to this procedure in accordance with its internal audit schedule, and all areas are considered under continuous audit by QA with respect to material handling. The maintenance of electrostatic discharge prevention methods is verified by QA through periodic audits. All hardware items are packaged and protected according to contract requirements and are verified by inspection. Evidence of inspection of packaging is recorded on the applicable shipping document.

## (D) - <u>Failure History</u>

All field and flight failures were reviewed. The failures identified occurred in circuitry identical to the current hardware configuration; MSHIS-GS and MSHIS-UR are included. There have been 7 failures resulting in erroneous output. There were 3 transmitter failures, 1 intermittent waveguide switch problem, 1 waveguide which had RF leakage, and 2 out of sync/out of balance antenna problems. Erroneous output failures typically are detected at system power up, and generally do not occur during system operation. Since the MSHIS Ground Station at all Shuttle landing sites are powered up daily beginning 4 or 5 days prior to a mission, and again 4 hours before a landing, an erroneous output failure most likely would be detected and corrected before a Shuttle landing.

#### SHITTLE CRITICAL ITEMS LIST - MSBLS GROUND STATION

SUBSYSTEM: GROUND STATION - MSBLS FMEA NO.: 05-2MO-00002 REV: 7 Sept 89

#### (E) - OPERATIONAL USE

For lower ceilings (8,000 to 10,000 feet) or night operations, redundant MSBIS (single-fault tolerance) is required for landing on a concrete runway. MSBIS is also mandatory for daylight landings on the lakebed with reduced ceilings, but is not required to be redundant. Deorbit is not attempted if the ceiling is less than 8,000 feet to ensure good visibility at low altitude. If radar tracking data (available at Edwards, KSC, and Northrop only) and ground communications are available, the MCC can attempt to resolve a MSBIS dilemma. Remote control operators are trained to evaluate system health and recognize probable failure modes from the Remote Control Unit Display. The Remote Control Unit Display is monitored to determine the nature of the malfunction (hard failure, intermittent, or random) and advise the chain of command on the status and the estimated time to restore operation.